

Estilo Exclusive Gardens: Annies Tehubijuluw 13-05-2015

Pictures of bad parts of the Irrigation system Miragolf Village.
This was found after the start of the maintenance.

1		<p>Several sprayers were damaged and thereby losing a lot of water. These have been replaced.</p>
2		<p>A tube was found underneath the surface after testing the system. It had a straight cut damage. This has been repaired.</p>
3		<p>A tube was found underneath the surface after testing the system. It had a straight cut damage. This has been repaired.</p>