





Estilo Exclusive Gardens: Annies Tehubijuluw 01-03-2015

Pictures of bad parts of the Irrigation system Miragolf Village.  
This is how it was found at the start of the maintenance.

|   |  |   |
|---|--|---|
| 1 |  | <p>Nelson irrigation controller.<br/>A very old brand and model.<br/>It is wise to replace it by a new one.</p> |
| 2 |  | <p>Electro valves need to be checked<br/>for damage and leakage.</p>  |
| 3 |  | <p>Electro valves need to be checked<br/>for damage and leakage.</p>  |

|   |  |  |
|---|--|--|
| 4 |   | <p>Electro valves need to be checked for damage and leakage.</p> |
| 5 |  | <p>Electro valves need to be checked for damage and leakage.</p> |